

Ohio EPA DSW Storm Water Section, Construction Site Visit Information Form

Inspector initials: JS Visit date: 7/10/13 Permit # 1604670-AG

Site Name: 93 Bed Nursing & Rehabilitation Facility

Site Address: Cincinnati - Dayton Road Middletown, OH

People Contacted On Site: _____

Phone: _____ E-mail: _____

1. Did you see the following on site?

ITEM	YES	NO	Not Requested	Comments
NOI			/	
Coverage Letter			/	No one on site
SWP3			/	
Inspection Records			/	
Contractor & Subs signature document			/	

2. Acreage Disturbed: 12.00

3. Site Status: Clearing/grubbing Rough Grading Storm sewers in
 Streets in Utilities installed Final Grade Final stabilization

4. Are BMPs needed: Not yet

5. Are BMPs effective? All Some None No BMPs

Explain: When earth disturbance begins, use silt fence/mulch berm

6. What post construction controls are shown on the SWP3? N/A

7. Were Photos taken & saved? NO

8. Was an NOV issued? NO

Additional notes/comments:

Project Just started