



John R. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Nally, Director

July 12, 2013

Mr. Steve Hartke
Butler County Engineers
1921 Fairgrove Avenue
Hamilton, OH 45011

**RE: Kyles Station Road at Lesourdsville West Chester Road; NPDES Permit #
1GC04244*AG; Compliance Inspection Findings**

Dear Mr. Hartke:

On Wednesday, July 10, 2013, I inspected the Kyles Station Road at Lesourdsville West Chester Road project near Hamilton, Ohio to determine compliance with the site's NPDES construction site storm water discharge permit. No one was at the site during the inspection.

Based on my observations, there were no obvious violations of the project's storm water discharge permit. I did not review the sediment control inspection logs or the site's storm water pollution prevention plan before my inspection.

As a reminder, please note that when construction is complete, and all areas of the site have been permanently stabilized with vegetation or other ground cover, the construction permit must be terminated. A one page "notice of termination" (NOT) form found at http://www.epa.ohio.gov/Portals/35/permits/General_NOT.pdf must be completed and sent to the following address:

Ohio Environmental Protection Agency
General Permit Program
PO Box 1049
Columbus, OH 43216-1049

No response to this letter is needed.

If you have any questions regarding the NPDES permit you can contact me at (937) 204-1002 or via email at james.schwieterman@epa.ohio.gov.

Sincerely,

James Schwieterman
Storm Water Group
Division of Surface Water

JS/kb

ec: Melissa Taylor

Ohio EPA DSW Storm Water Section, Construction Site Visit Information Form

Inspector initials: JS Visit date: 7/10/13 Permit # 16C04244-AG

Site Name: Kyles Station Road at Leesardsville West Chester

Site Address: Hamilton, OH Butler County

People Contacted On Site: _____

Phone: _____ E-mail: _____

1. Did you see the following on site?

ITEM	YES	NO	Not Requested	Comments
NOI			✓	
Coverage Letter			✓	
SWP3			✓	
Inspection Records			✓	
Contractor & Subs signature document			✓	

2. Acreage Disturbed: 2.5

3. Site Status: Clearing/grubbing Rough Grading Storm sewers in
 Streets in Utilities installed Final Grade Final stabilization

4. Are BMPs needed: NO

5. Are BMPs effective? All Some None No BMPs

Explain: _____

6. What post construction controls are shown on the SWP3? N/A

Storm Drain Sewer System

7. Were Photos taken & saved? NO

8. Was an NOV issued? N/A

Additional notes/comments:
NOT for site