



John R. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Nally, Director

July 11, 2013

Bruns General Contracting
3050 South Tipp Cowlesville Road
Tipp City, OH 45371

RE: St. George Russian Orthodox Church; NPDES Permit # 1GC04246*AG; Construction Site Inspection

To Whom It May Concern:

On Tuesday July 9, 2013, I inspected the St. George Russian Orthodox Church located at 118 North Lebanon Road in Loveland, Ohio, to determine compliance with its NPDES construction site storm water discharge permit. I stopped in at the job trailer however no one was in there so I proceeded to walk the site.

I did not review sediment control inspection logs, or the site's storm water pollution prevention plan (SWPPP).

I did notice that at the rear of the site there was an area where the mulch berm has failed and turbid water is leaving the site (see attached photo). However, because it is indicated in the approved permit that the receiving Municipal Separate Storm Sewer System (MS4) is the city of Loveland, I have reason to believe that the failure in this area may not be an issue. To confirm or deny this conclusion I ask that you please **send a copy of the sites SWPPP to the Ohio EPA Southwest District Office via mail or email for review by July 26, 2013.**

If you have questions regarding this letter you can contact me at (937) 204-1003, or via email at eric.damian@epa.ohio.gov.

Sincerely,

A handwritten signature in black ink, appearing to read "Eric Damian", is written over a horizontal line.

Eric Damian
Storm Water Group
Division of Surface Water

ED/kb

Enclosure: Inspection Form
Inspection Photo

Ohio EPA DSW Storm Water Section, Construction Site Visit Information Form

Inspector initials: ESD Visit date: 7/9/18 Permit # 1GC04246*AG

Site Name: St. George Russian Orthodox Church

Site Address: 118 N Lebanon Rd.

People Contacted On Site: none

Phone: _____ E-mail: _____

1. Did you see the following on site?

ITEM	YES	NO	Not Requested	Comments
NOI				
Coverage Letter				
SWP3				ask for in letter
Inspection Records				
Contractor & Subs signature document				

2. Acreage Disturbed: 1.82

3. Site Status: Clearing/grubbing Rough Grading Storm sewers in
 Streets in Utilities installed Final Grade Final stabilization

4. Are BMPs needed: no

5. Are BMPs effective? All Some None No BMPs
 Explain: silt fence and or mulch berms around entire site

6. What post construction controls are shown on the SWP3? n/a

7. Were Photos taken & saved? yes 8. Was an NOV issued? no

Additional notes/comments:

- no one in job trailer call work being done inside building
- mulch berm failure in back of site, failure an issue?



07/09/2013 11:31