



July 11, 2013

Tucker Bohm
The Daimler Group
1533 Lake Shore Drive
Columbus, OH 43204

**RE: Construction Storm Water Inspection at New Albany Center of Technology/
Franklin County, Permit Number: 4GC04056*AG**

Dear Mr. Bohm:

This letter is written regarding a storm water inspection conducted by Brittany Turner and Rachel Bellis of the Ohio EPA at New Albany Center of Technology located on the south side of west Campus Road, west of New Albany Road on July 1, 2013. The purpose of the inspection was to evaluate compliance with the General Storm Water Permit associated with Construction Activities. During the inspection, our staff noted the following issues associated with construction activities at this site:

Sediment and Erosion Control:

- Failed silt fence was noted along the southern portion of the site. Please ensure corrective measures are implemented within three (3) days from receipt of this letter (See Figures 1 & 2).
- A bleeder ditch exists along the southern most sediment basin. This bleeder must be rerouted into the basin or eliminated (See Figure 3).
- At the time of the inspection, we were unclear as to the intended function of the northern basin. It appears to be utilized as a sediment basin. The basin must incorporate a modified outlet structure, specific for sediment control. In addition, it appears to be more than 50 percent full of sediment and in accordance with the permit, must be cleaned. (See Figure 4).
- The inlet protections noted on Limon drive have failed and are not working as intended (See Figure 5).

Tucker Bohm
The Daimler Group
Page -2-

- Be aware the General Permit states that all barren areas which remain idle in excess of 21 days must be protected from erosion within seven days of the last earth disturbing activities. In addition, erosion protection must be implemented for all areas of final grade within seven (7) days (See Figure 6).

If you have any questions regarding this letter or the inspection, please do not hesitate to contact me at our Central District Office at 614-728-3844 or email at harry.kallipolitis@epa.state.oh.us. In addition, please provide a written response (**email preferred**) to the action items addressed above within ten days from receipt of this letter. A follow up inspection will be conducted to ensure the minimum conditions of the General Permit have been met.

Sincerely



Harry Kallipolitis
Storm Water Coordinator
Ohio EPA
Division of Surface Water

c: Jeff Bohne, Water Quality Supervisor, DSW / CDO