



John R. Kasich, Governor  
Mary Taylor, Lt. Governor  
Scott J. Nally, Director

July 18, 2013

Mr. Marc Chiaramonte  
Cincinnati United Contractors, LLC  
7175 East Kemper Road  
Cincinnati, OH 45249

**RE: Hillman Fastener Parking Lot; NPDES Permit # 1GC04425\*AG; Construction Site Inspection**

Dear Mr. Chiaramonte:

On Tuesday, July 16, 2013, I inspected the Hillman Fastener Parking Lot located along Northwest Drive in Cincinnati, Ohio, to determine compliance with its NPDES construction site storm water discharge permit. I walked the perimeter of the property, but did not meet with anyone while at the site.

Based on my observations, there were no obvious violations of the project's storm water discharge permit. I did not review sediment control inspection logs, or the site's storm water pollution prevention plan (SWPPP).

As a reminder, please note that when construction is complete, and all areas of the site have been permanently stabilized with vegetation or other ground cover, the construction permit must be terminated. A one page "notice of termination" (NOT) form found at <http://www.epa.ohio.gov/Portals/35/permits/General NOT.pdf> must be completed and sent to the following address:

Ohio Environmental Protection Agency  
General Permit Program  
PO Box 1049  
Columbus, OH 43216-1049

If you have questions regarding this letter you can contact me at (937) 204-1003, or via email at [eric.damian@epa.ohio.gov](mailto:eric.damian@epa.ohio.gov).

Sincerely,

Eric Damian  
Storm Water Group  
Division of Surface Water

ED/kb

Enclosure: Inspection Form

Ohio EPA DSW Storm Water Section, Construction Site Visit Information Form

Inspector initials: EST Visit date: 7/16/13 Permit # 19C04425\*AG

Site Name: Hillman Fastener Parking Lot

Site Address: Northwest Drive

People Contacted On Site: none

Phone: \_\_\_\_\_ E-mail: \_\_\_\_\_

1. Did you see the following on site?

ITEM	YES	NO	Not Requested	Comments
NOI				
Coverage Letter				
SWP3				
Inspection Records				
Contractor & Subs signature document				

2. Acreage Disturbed: 2

3. Site Status: Clearing/grubbing  
 Streets in      Rough Grading      Storm sewers in  
 Utilities installed      Final Grade      Final stabilization

4. Are BMPs needed: no

5. Are BMPs effective? All      Some      None      No BMPs  
 Explain: inlet protection, silt fence in some areas

6. What post construction controls are shown on the SWP3? n/a

7. Were Photos taken & saved? yes      8. Was an NOV issued? no

Additional notes/comments:  
 - all bare dirt in what will be the parking lot (below grade of surrounding area)  
 - seeding taking hold out side of where lot will be