



John R. Kasich, Governor  
Mary Taylor, Lt. Governor  
Scott J. Nally, Director

July 18, 2013

Mr. Bradley Neavin  
Eaton Community Schools  
307 North Cherry Street  
Eaton, OH 45320

**RE: New Athletic Facilities-Phase 1; NPDES Permit #1GC04459\*AG; Compliance Inspection Findings**

Dear Mr. Neavin:

On Tuesday, July 16, 2013, I inspected the Eaton Middle School site in Eaton, Ohio, to determine compliance with the site's NPDES construction site storm water discharge permit. I did not speak with anyone during the inspection. The reason for the inspection was for a follow-up from the Notice of Violation issued June 13, 2013.

Based on my observations, there were no obvious violations of the project's storm water discharge permit. I did review the sediment control inspection logs and the site's storm water pollution prevention plan before my inspection. The corrective action for the silt fence, located along the north end of the site, has been conducted. The short section of silt fence is now reinforced and is minimizing sediment laden water from washing off the site. Proper maintenance of silt fence was completed and shall be maintained until all up slope areas are stabilized. This corrective action is now complying with the NPDES general construction permit.

Any disturbed areas within 50 feet of a surface water of the state and not at final grade must be temporarily stabilized within two days of the most recent disturbance if the area will remain idle for more than 14 days. Also, any disturbed areas not within 50 feet of a surface water of the state and not at final grade must be temporarily stabilized within 7 days of the most recent disturbance if the area will remain idle for more than 14 days.

As a reminder, please note that when construction is complete, and all areas of the site have been permanently stabilized with vegetation or other ground cover, the construction permit must be terminated. A one page "notice of termination" (NOT) form found at [http://www.epa.ohio.gov/Portals/35/permits/General NOT.pdf](http://www.epa.ohio.gov/Portals/35/permits/General%20NOT.pdf) must be completed and sent to the following address:

Ohio Environmental Protection Agency  
General Permit Program  
PO Box 1049  
Columbus, OH 43216-1049

Mr. Bradley Neavin  
New Athletic Facilities-Phase 1  
July 18, 2013  
Page 2

No response to this letter is needed.

If you have any questions regarding the NPDES permit you can contact me at (937) 204-1002 or via email at [james.schwieterman@epa.ohio.gov](mailto:james.schwieterman@epa.ohio.gov).

Sincerely,

A handwritten signature in black ink, appearing to read "James Schwieterman", written in a cursive style.

James Schwieterman  
Storm Water Group  
Division of Surface Water

JS/kb

ec: Tom Doseck, Eaton Community Schools  
Tony Quinter, GDCG  
Josh Mumpower, GDCG  
James Skipper, GDCG

Enclosed: Inspection Sheet

Ohio EPA DSW Storm Water Section, Construction Site Visit Information Form

Inspector initials: JS Visit date: 7/16/13 Permit # 150045

Site Name: New Athletic Facilities - 1, Eton U. School

Site Address: 11111 Harst Eton, OH, 43017 County

People Contacted On Site: \_\_\_\_\_

Phone: \_\_\_\_\_ E-mail: \_\_\_\_\_

1. Did you see the following on site? on-line

| ITEM                                 | YES                                 | NO                       | Not Requested            | Comments     |
|--------------------------------------|-------------------------------------|--------------------------|--------------------------|--------------|
| NOI                                  | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |              |
| Coverage Letter                      | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | From 6/13/13 |
| SWP3                                 | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | in file      |
| Inspection Records                   | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |              |
| Contractor & Subs signature document | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |              |

2. Acreage Disturbed: 15.0 + 18.9

3. Site Status: Clearing/grubbing  Rough Grading  Storm sewers in  
Streets in  Utilities installed  Final Grade  Final stabilization

4. Are BMPs needed: Yes, permanent  occurs

5. Are BMPs effective? All  Some  None  No BMPs

Explain: Silt fence  Intert. Retention

6. What post construction controls are shown on the SWP3? Yes, silt fence

7. Were Photos taken & saved?

8. Was an NOV issued?

Additional notes/comments:

Final stabilization once all disturbance activities have concluded  
 corrective Actions  with permit  
 1/2 acre parking lot near construction