



John R. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Nally, Director

July 18, 2013

Mr. Tim Edwards
Ramsey Development LLC
706 Jefferson Street
Tell City, IN 47586

RE: Greenville Health Campus; NPDES Permit #1GC04638*AG; Compliance Inspection Findings

Dear Mr. Ramsey:

On Tuesday, July 16, 2013, I inspected the Greenville Health Campus site in Greenville, Ohio, to determine compliance with the site's NPDES construction site storm water discharge permit. I did not speak with anyone during the inspection.

Based on my observations, there were no obvious violations of the project's storm water discharge permit. I did not review the sediment control inspection logs or the site's storm water pollution prevention plan before my inspection, but records of inspections of the erosion control BMPs are required to be kept.

All best management practices seem to be working efficiently at this point. Just a reminder, that any disturbed areas that will be dormant for more than 14 days require temporary stabilization within seven days of the most recent disturbance within the area.

No response to this is letter is needed.

If you have any questions regarding the NPDES permit you can contact me at (937) 204-1002 or via email at james.schwieterman@epa.ohio.gov.

Sincerely,

A handwritten signature in black ink, appearing to read 'James Schwieterman', with a long horizontal line extending to the right.

James Schwieterman
Storm Water Group
Division of Surface Water

JS/kb

Enclosed: Inspection Sheet

Ohio EPA DSW Storm Water Section, Construction Site Visit Information Form

Inspector initials: JS Visit date: 7/16/13 Permit # 16C04638-A6

Site Name: Greenville Health Campus

Site Address: 1315 Kitchin Mill Way Greenville, OH 45426

People Contacted On Site: _____

Phone: _____ E-mail: _____

1. Did you see the following on site?

ITEM	YES	NO	Not Requested	Comments
NOI			/	D.L. talk with engineer at the site.
Coverage Letter			/	
SWP3			/	
Inspection Records			/	
Contractor & Subs signature document			/	

2. Acreage Disturbed: 0.4

3. Site Status: Clearing/grubbing
 Streets in _____ Utilities installed Rough Grading Final Grade Storm sewers in Final stabilization _____
- being installed

4. Are BMPs needed: Yes

5. Are BMPs effective? All Some None No BMPs

Explain: Silt fence around perimeter

6. What post construction controls are shown on the SWP3? N/A

Storm sewer being installed

7. Were Photos taken & saved? Yes 8. Was an NOV issued? NO

Additional notes/comments: