

John D. Kasich, Governor
Mike Taylor, Lt. Governor
Scott J. Walsh, Director

July 25, 2013

Edward A. den Haan
The Abigail House
One Whitebarn Road
New Albany, OH 43054

Re: Construction Storm Water Inspection at Abigail House Northwoods Lane / Franklin County. Permit Number: 4GC03924 *AG

Dear Mr. den Haan:

This letter is written regarding a storm water inspection conducted by Brittany Turner and Jerome Hoke of the Ohio EPA at The Abigail House Northwoods Lane located at One Whitebarn Road on July 3, 2013. The purpose of the inspection was to evaluate compliance with the General Storm Water Permit associated with Construction Activities. During the inspection, our staff noted the following issues associated with construction activities at this site:

Sediment and Erosion Control:

- The silt fence on site has failed and will require maintenance at this time. (See Figure 1).
- Be aware the General Permit states that all barren areas which remain idle in excess of 21 days must be protected from erosion within seven days of the last earth disturbing activities. In addition, erosion protection must be implemented for all areas of final grade within seven (7) days (See Figure 2).

If you have any questions regarding this letter or the inspection, please do not hesitate to contact me at our Central District Office at 614-728-3844 or email at harry.kallipolitis@epa.state.oh.us.

Sincerely,

A handwritten signature in black ink, appearing to read "Harry Kallipolitis", written over a faint circular stamp.

Harry Kallipolitis
Storm Water Coordinator
Division of Surface Water
Central District Office

HK/nsm Abigail House Northwoods Lane 7-3-2013




Figure 1: Silt fence over capacity




Figure 2: Barron area