

Ohio EPA DSW Storm Water Section, Construction Site Visit Information Form

Inspector initials: JS Visit date: 7/30/13 Permit # 16004652-A6

Site Name: Dollar General - Millville Avenue

Site Address: 1402 Millville Ave. Hamilton, OH Butler County

People Contacted On Site: _____

Phone: _____ E-mail: _____

1. Did you see the following on site?

ITEM	YES	NO	Not Requested	Comments
NOI			✓	
Coverage Letter			/	
SWP3			/	
Inspection Records			/	
Contractor & Subs signature document			/	

2. Acreage Disturbed: 1.56

Project Not started

3. Site Status: Clearing/grubbing Rough Grading Storm sewers in
 Streets in Utilities installed Final Grade Final stabilization

4. Are BMPs needed: N/A

5. Are BMPs effective? All Some None No BMPs

Explain: N/A

6. What post construction controls are shown on the SWP3? N/A

7. Were Photos taken & saved? NO

8. Was an NOV issued? NO

Additional notes/comments:

- Current Building still exist / needs to be demolished
- Not started