



John R. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Mally, Director

July 31, 2013

Mark Waite
Franklin County Engineer
960 Dublin Road
Columbus, Ohio 43215

Complaint Investigation

Dear Mr. Waite,

This is a follow up letter to a complaint received on July 15, 2013. The complaint alleged the placement of non-erodible fill adjacent to Blacklick Creek near the Livingston Avenue Bridge.

Our staff evaluated the fill on July 15, 2013, and found evidence of concrete debris near the bridge. At this time we are inquiring as to the nature of the fill and request removal in the event it is not affiliated with any pending construction. Included in this letter are pictures of the area for your reference.

If you have any questions regarding this letter or the inspection, please do not hesitate to contact me at our Central District Office at 614-728-3844 or email at harry.kallipolitis@epa.state.oh.us.

Sincerely

Harry Kallipolitis
Storm Water Coordinator
Ohio EPA
Division of Surface Water

c: Jeff Bohne, Water Quality Supervisor, DSW / CDO

HK/slw

Livingston Avenue Bridge 7-15-13




Figure 1 North side of Livingston Avenue Bridge (39.945891,-82.799777)



Figure 2 South side of Livingston Avenue Bridge.



Figure 3 Close up of the north side of the bridge.