



John R. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Nally, Director

August 1, 2013

R B Jergens Contractors Inc.
11418 North Dixie Drive
Vandalia, Ohio 45414

**RE: Closed Old River Valley Place of Nature Foundation; NPDES Permit #1GC03735*AG
Compliance Inspection Findings**

To Whom it May Concern:

On Tuesday, July 30, 2013, I inspected the Closed Old River Valley Place of Nature Foundation site in Hamilton, Ohio, to determine compliance with the site's NPDES construction site storm water discharge permit. I did not speak with any during the inspection.

Based on my observations, there were no obvious violations of the project's storm water discharge permit. I did not review the sediment control inspections logs or the site's storm water pollution prevention plan before my inspection. The project is complete and grass is established on the site.

As a reminder, please note that when construction is complete, and all areas of the site have been permanently stabilized with vegetation or other ground cover, the construction permit must be terminated. A one page "Notice of Termination" (NOT) Form found at http://www.epa.ohio.gov/Portals/35/permits/General_NOT.pdf must be completed and sent to the following address:

Ohio Environmental Protection Agency
General Permit Program
P.O. Box 1049
Columbus, OH 43216-1049

If you have any questions regarding the NPDES permit, you can contact me at (937) 204-1002 or via email james.schwieterman@epa.ohio.gov.

Sincerely,

James Schwieterman
Storm Water Group
Division of Surface Water

JS/tb

Enclosed: Inspection Sheet

Ohio EPA DSW Storm Water Section, Construction Site Visit Information Form

Inspector initials: JS Visit date: 7/20/13 Permit # 16603735-A6

Site Name: Closed Old River Valley Place of N. to

Site Address: 2611 Hamilton (Leves Road (SR 128) Hamilton, OH Butler Co.

People Contacted On Site: _____

Phone: _____ E-mail: _____

1. Did you see the following on site?

ITEM	YES	NO	Not Requested	Comments
NOI			/	
Coverage Letter			/	
SWP3			/	
Inspection Records			/	
Contractor & Subs signature document			/	

2. Acreage Disturbed: 9.0

3. Site Status: Clearing/grubbing Rough Grading Storm sewers in
 Streets in Utilities installed Final Grade Final stabilization

4. Are BMPs needed: NO

5. Are BMPs effective? All Some None No BMPs

Explain: NO

6. What post construction controls are shown on the SWP3? NO

7. Were Photos taken & saved? NO

8. Was an NOV issued? NO

Additional notes/comments:

File a NOT