



John R. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Nally, Director

August 1, 2013

Ms. Norma Pennock
Southwest Regional Water District
3640 Old Oxford Road
Hamilton, Ohio 45013

**RE: Hamilton Scipio Water Main Replacement; NPDES Permit #1GC04649*AG
Compliance Inspection Findings**

Dear Ms. Pennock:

On Tuesday, July 30, 2013, I inspected the Hamilton Scipio Water Main Replacement project in Hamilton, Ohio, to determine compliance with the site's NPDES construction site storm water discharge permit. You were on site during the inspection along with Jay Smith of Smith Corp.

Based on my observations, there were no obvious violations of the project's storm water discharge permit. I did not review the sediment control inspections logs or the site's storm water pollution prevention plan before my inspection, but records of inspections of the erosion control BMPs are required to be kept.

Please use best management practices throughout the water main replacement project. An area for concern, on site, is the construction phase when the water main crosses Lick Run. Use necessary erosion control practices to prevent any sediment laden water from entering a state of Ohio water way.

No response to this letter is needed.

If you have any questions regarding the NPDES permit, you can contact me at (937) 204-1002 or via email james.schwieterman@epa.ohio.gov.

Sincerely,

James Schwieterman
Storm Water Group
Division of Surface Water

JS/tb

EC: Jay Smith

