



John R. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Nally, Director

August 5, 2013

Mr. William H. Staebler
2333 Richmond Road, Suite 350
Beechwood, Ohio 44122

**RE: McDonalds-Woodman Drive; NPDES Permit 1GC04347*AG
Compliance Inspection Findings**

Dear Mr. Staebler:

On Thursday, August 1, 2013, I inspected the McDonalds-Woodman Drive site in Riverside, Ohio to determine compliance with the site's NPDES construction site storm water discharge permit. No one was at the site during the inspection.

Based on my observations, there were no obvious violations of the project's storm water discharge permit. I did not review the sediment control inspections logs or the site's storm water pollution prevention plan before my inspection.

As a reminder, please note that when construction is complete, and all areas of the site have been permanently stabilized with vegetation or other ground cover, the construction permit must be terminated. A one page "Notice of Termination" form, found at [www.epa.ohio.gov/Portals/35/permits/General NOT.pdf](http://www.epa.ohio.gov/Portals/35/permits/General_NOT.pdf), must be completed and sent to the following address:

Ohio Environmental Protection Agency
General Permit Program
P. O. Box 1049
Columbus, Ohio 43216-1049

No response to this letter is needed.

If you have any questions regarding the NPDES permit, you can contact me at (937) 204-1002 or by email at james.schwieterman@epa.ohio.gov.

Sincerely,

James Schwieterman
Storm Water Group
Division of Surface Water

JS/tb

Enclosed: Inspection Sheet

Ohio EPA DSW Storm Water Section, Construction Site Visit Information Form

Inspector initials: JS Visit date: 8/11/13 Permit # 16001347 AG

Site Name: McDonalds - Woodman Ave. Dayton

Site Address: 166 W. 122 Drive Riverside, OH 45431 Montgomery, 6

People Contacted On Site: _____

Phone: _____ E-mail: _____

1. Did you see the following on site?

ITEM	YES	NO	Not Requested	Comments
NOI			/	
Coverage Letter			/	
SWP3			/	
Inspection Records			/	
Contractor & Subs signature document			/	

2. Acreage Disturbed: 1.0

3. Site Status: Clearing/grubbing Streets in Rough Grading Utilities installed Storm sewers in Final Grade Final stabilization Final stabilization

4. Are BMPs needed: NO

5. Are BMPs effective? All Some None No BMPs

Explain: _____

6. What post construction controls are shown on the SWP3? _____

7. Were Photos taken & saved? NO 8. Was an NOV issued? NO

Additional notes/comments:
File a NOT / Grass Established