



John R. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Nally, Director

August 5, 2013

Mr. Mike Grever
Core Resources Inc.
1404 Vine Street
Cincinnati, Ohio 45202

**RE: Roto Rooter Service Center; NPDES Permit 1GC04572*AG
Compliance Inspection Findings**

Dear Mr. Grever:

On Thursday, August 1, 2013, I inspected the Roto Rooter Service Center in Miamisburg, Ohio to determine compliance with the site's NPDES construction site storm water discharge permit. I spoke with a contracted worker during the inspection.

Based on my observations, there were no obvious violations of the project's storm water discharge permit. I did not review the sediment control inspections logs or the site's storm water pollution prevention plan before my inspection.

As a reminder, please note that when construction is complete, and all areas of the site have been permanently stabilized with vegetation or other ground cover, the construction permit must be terminated. A one page "Notice of Termination" form, found at [www.epa.ohio.gov/Portals/35/permits/General NOT.pdf](http://www.epa.ohio.gov/Portals/35/permits/General_NOT.pdf), must be completed and sent to the following address:

Ohio Environmental Protection Agency
General Permit Program
P. O. Box 1049
Columbus, Ohio 43216-1049

No response to this letter is needed.

If you have any questions regarding the NPDES permit, you can contact me at (937) 204-1002 or by email at james.schwieterman@epa.ohio.gov.

Sincerely,

James Schwieterman
Storm Water Group
Division of Surface Water

JS/tb

Enclosed: Inspection Sheet

ec: Rich McFarland, Field Manager, Core Resources, Inc.

Ohio EPA DSW Storm Water Section, Construction Site Visit Information Form

Inspector initials: JS Visit date: 8/11/31 Permit # 16C04699 9A6

Site Name: ROTO FILTER SERVICE CENTER

Site Address: 9490 G... Rd, Mariamsville, OH

People Contacted On Site: Rich McFarland - Field Manager

Phone: 513-200-4447 E-mail: rmcfarland@corp-1.com

1. Did you see the following on site?

ITEM	YES	NO	Not Requested	Comments
NOI	/			
Coverage Letter	/			
SWP3	/			
Inspection Records	/			
Contractor & Subs signature document			/	

2. Acreage Disturbed: 7.0

3. Site Status: Clearing/grubbing Rough Grading Storm sewers in ...

Streets in ... Utilities installed ... Final Grade ... Final stabilization ...

4. Are BMPs needed: Yes, Sediment Trap, Silt Fence, Inlet Protection, Stormwater Entrance

5. Are BMPs effective? All Some None No BMPs

Explain: Silt Fence in buffer strip near wooded area

6. What post construction controls are shown on the SWP3? Silt fence around building and driveway

7. Were Photos taken & saved? Yes 8. Was an NOV issued? NO

Additional notes/comments:
 - Advise maintenance on ...
 - Silt fence when necessary