

Ohio EPA DSW Storm Water Section, Construction Site Visit Information Form

Inspector initials: JS Visit date: 8/5/13 Permit # 16C047076 *A6

Site Name: Pioneer Rural Electric Cooperative Inc.

Site Address: 344 West US Route 36 Piqua, OH Miami County

People Contacted On Site: _____

Phone: _____ E-mail: _____

1. Did you see the following on site?

ITEM	YES	NO	Not Requested	Comments
NOI				 No one on site
Coverage Letter				
SWP3				
Inspection Records				
Contractor & Subs signature document				

2. Acreage Disturbed: 2.38

3. Site Status: Clearing/grubbing Rough Grading Storm sewers in
 Streets in Utilities installed Final Grade Final stabilization

4. Are BMPs needed: NO

5. Are BMPs effective? All Some None No BMPs

Explain: _____

6. What post construction controls are shown on the SWP3? N/A

7. Were Photos taken & saved? NO

8. Was an NOV issued? NO

Additional notes/comments:

Project Not started