



John R. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Neilly, Director

August 6, 2013

Robert Priestas
City of Marysville
125 East Sixth Street
Marysville, OH 43040

**Re: Construction Storm Water Inspection at Marysville Municipal Service Complex /
Union County. Permit Number: 4GC03915*AG**

Dear Mr. Priestas:

This letter is written regarding a storm water inspection conducted by Rachel Bellis and Elizabeth Pleta, of the Ohio EPA at the Marysville Municipal Service Complex located at 209 South Main Street on July 22, 2013. The purpose of the inspection was to evaluate compliance with the General Storm Water Permit associated with Construction Activities. During the inspection, our staff noted the following issues associated with construction activities at this site:

Sediment and Erosion Control:

- Please continue to maintain all inlet protections (See Figures 1 & 2).

If you have any question regarding this letter or the inspection, please do not hesitate to contact me at our Central District Office at (614) 728-3844 or email at harry.kallipolitis@epa.state.oh.us. A follow-up inspection will be conducted to ensure the conditions of the General Permit are met.

Sincerely,

Harry Kallipolitis
Storm Water Coordinator
Division of Surface Water
Ohio EPA

HK/nsm Marysville Municipal Service Complex 7-22-13



Figure 1. Inlet protection.




Figure 2. Inlet protection.