



John R. Kasich, Governor  
Mary Taylor, Lt. Governor  
Scott J. Nally, Director

August 6, 2013

David Gilmore  
Meijer Inc.  
2929 Walker Avenue Northwest  
Grand Rapids, MI, 49544

**Re: Construction Storm Water Inspection at Meijer Store Number 235/ Union County  
Permit Number: 4GC04041 \*AG**

Dear Mr. Gilmore:

This letter is written regarding a storm water inspection conducted by Rachel Bellis and Elizabeth Pleta of the Ohio EPA at Meijer Store Number 235 located at Coleman's Crossing Boulevard on July 22, 2013. The purpose of the inspection was to evaluate compliance with the General Storm Water Permit associated with Construction Activities. During the inspection, our staff noted the following issues associated with construction activities at this site:

**Sediment and Erosion Control:**

- During the inspection, it appeared that the sediment pond on the northeast corner of the site requires stabilization around the perimeter (see Figure 1).
- Be aware the General Permit states that all barren areas which remain idle in excess of 21 days must be protected from erosion within seven days of the last earth disturbing activities. In addition, erosion protection must be implemented for all areas of final grade within seven (7) days.
- The silt fence appeared to be functioning as intended.

If you have any questions regarding this letter or the inspection, please do not hesitate to contact me at our Central District Office at 614-728-3844 or email at [harry.kallipolitis@epa.state.oh.us](mailto:harry.kallipolitis@epa.state.oh.us).

Sincerely,

Harry Kallipolitis  
Storm Water Coordinator  
Division of Surface Water  
Central District Office

HK/nsm Meijer Store No 235 7-22-2013



**Figure 1: Areas surrounding the sediment basin require stabilization.**