



John R. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Nally, Director

August 6, 2013

Upper Valley Community Church
1400 Seidel Parkway
Piqua, Ohio 45356

**RE: Upper Valley Community Church; NPDES Permit # 1GC04045*AG;
Compliance Inspection Findings**

To Whom It May Concern:

On Monday, August 5, 2013, I inspected the Upper Valley Community Church site in Piqua, Ohio to determine compliance with the site's National Pollutant Discharge Elimination System (NPDES) construction site storm water discharge permit. I did not speak with anyone at the site.

Based on my observations, there were no obvious violations of the project's storm water discharge permit. I did not review the sediment control inspections logs or the site's Storm Water Pollution Prevention Plan (SWP3) before my inspection. The project is now complete and grass is established on the site.

As a reminder, please note that when construction is complete, and all areas of the site have been permanently stabilized with vegetation or other ground cover, the construction permit must be terminated. A one page "Notice of Termination" (NOT) form found at http://www.epa.ohio.gov/Portals/35/permits/General_NOT.pdf must be completed and sent to the following address:

Ohio Environmental Protection Agency
General Permit Program
P. O. Box 1049
Columbus, OH 43216-1049

No response to this letter is needed.

Upper Valley Community Church
August 6, 2013
Page 2

If you have any questions regarding the NPDES permit you can contact me at (937) 204-1002 or by via email james.schwieterman@epa.ohio.gov.

Sincerely,

A handwritten signature in black ink, appearing to read "James Schwieterman", with a long horizontal flourish extending to the right.

James Schwieterman
Storm Water Group
Division of Surface Water

Enclosure: Inspection Sheet

JS/bp

Ohio EPA DSW Storm Water Section, Construction Site Visit Information Form

Inspector initials: JS Visit date: 8/5/13 Permit # IGC04045-AG

Site Name: Upper Valley Community Church

Site Address: 1400 Seidel Parkway Piqua, OH Miami County

People Contacted On Site: _____

Phone: _____ E-mail: _____

1. Did you see the following on site?

ITEM	YES	NO	Not Requested	Comments
NOI				
Coverage Letter				
SWP3				
Inspection Records				
Contractor & Subs signature document				

2. Acreage Disturbed: 1.5

3. Site Status: Clearing/grubbing Rough Grading Storm sewers in
Streets in Utilities installed Final Grade Final stabilization

4. Are BMPs needed: NO

5. Are BMPs effective? All Some None No BMPs

Explain: _____

6. What post construction controls are shown on the SWP3? N/A

7. Were Photos taken & saved? NO 8. Was an NOV issued? NO

Additional notes/comments:

Project complete / Grass Established
 File a NOT