



John R. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Nally, Director

August 12, 2013

Mr. Paul Myers
Village of St. Bernard
110 Washington Avenue
St. Bernard, Ohio 45217

**RE: Village of St. Bernard Service Center; NPDES Permit # 1GC04484*AG
Construction Site Inspection**

Dear Mr. Myers:

On Friday, August 9, 2013, I inspected the village of St. Bernard Service Center construction site located in St. Bernard, Ohio, to determine compliance with its NPDES construction site storm water discharge permit. I walked the property and met with you, Walt Moeller, and Greg Curson.

Based on my observations, there were no obvious violations of the project's storm water discharge permit. I did not review sediment control inspection logs, or the site's storm water pollution prevention plan (SWP3).

As a reminder, compliance with the permit must be upheld until construction is complete, and all areas of the site have been permanently stabilized with vegetation or other ground cover. Once final stabilization is achieved, the construction permit must be terminated by completing the one page "notice of termination" (NOT) form found at http://www.epa.ohio.gov/Portals/35/permits/General_NOT.pdf and sending it to the following address:

Ohio Environmental Protection Agency
General Permit Program
P.O. Box 1049
Columbus, Ohio 43216-1049

If you have questions regarding this letter, you can contact me at (937) 204-1003, or via email at eric.damian@epa.ohio.gov or Chris Cotton at (937) 285-6442 and chris.cotton@epa.ohio.gov.

Sincerely,

Eric Damian
Storm Water Group
Division of Surface Water

ED/tb

Enclosure: Inspection Form

cc: Greg Curson, Superintendent, Performance Construction

Ohio EPA DSW Storm Water Section, Construction Site Visit Information Form

Inspector initials: EST Visit date: 8/19/13 Permit # 1GCO4484*AG

Site Name: Village of St. Bernard Service Center

Site Address: 5230 Vine St.

People Contacted On Site: Paul Myers; Walt Moeller; Greg Curson

Phone: Greg-(513)-598-5100 E-mail: GSCZ@FUSE.net

1. Did you see the following on site?

ITEM	YES	NO	Not Requested	Comments
NOI				
Coverage Letter				
SWP3				
Inspection Records				
Contractor & Subs signature document				

2. Acreage Disturbed: 2.7

3. Site Status: Clearing/grubbing
 Streets in Utilities installed Final Grade Final stabilization

Rough Grading

Storm sewers in

4. Are BMPs needed: no

5. Are BMPs effective? All Some None No BMPs

Explain: silt fence, inlet protection, concrete wash out

6. What post construction controls are shown on the SWP3? n/a

7. Were Photos taken & saved? no

8. Was an NOV issued? no

Additional notes/comments:

- working for \approx 2 months, estimated comp. Feb./Mar. 2014
- silt fence good
- stm ties into existing stm
- good const. entrance
- roll of demposters