



August 23, 2013

Walter Novembre
Leslie Wexner
One White Barn
New Albany, OH 43054

Re: Construction Storm Water Inspection at Abigail House Northwoods Lane / Franklin County. Permit Number: 4GC03924*AG

Dear Mr. Novembre,

This letter is written regarding a storm water inspection conducted by Rachel Bellis and Elizabeth Pleta of the Ohio EPA at Abigail House Northwoods Lane located at 4243 Kitzmiller Road on August 1, 2013. The purpose of the inspection was to evaluate compliance with the General Storm Water Permit associated with Construction Activities. During the inspection, our staff noted the following issues associated with construction activities at this site:

Sediment and Erosion Control:

- The sediment and erosion controls at this site are currently functioning properly. Please continue to monitor and ensure continued compliance with the General Storm Water Permit Associated with Construction Activities.
- Be aware the General Permit states that all barren areas which remain idle in excess of 21 days must be protected from erosion within seven days of the last earth disturbing activities. In addition, erosion protection must be implemented for all areas of final grade within seven (7) days.

If you have any question regarding this letter or the inspection, please do not hesitate to contact me at our Central District Office at (614) 728-3844 or email at harry.kallipolitis@epa.state.oh.us. A follow-up inspection will be conducted to ensure the conditions of the General Permit are met.

Sincerely,

Harry Kallipolitis
Storm Water Coordinator
Division of Surface Water
Central District Office

HK/nsm Abigail House Northwoods Lane 8-1-13