



John R. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Nally, Director

Re: Marion County
Morning View Care Center
NPDES Permit

August 28, 2013

Mr. Greg Bratton
Morning View Care Center
677 Marion-Cardington Road
Marion, Ohio 43302

Dear Mr. Bratton:


On August 21, 2013, an operation and maintenance inspection was made of the wastewater treatment plant (WWTP) serving Morning View Pointe. The care center is located at 677 Marion-Cardington Road, Pleasant Township, Marion County. This inspection was conducted to evaluate compliance with your facility's National Pollutant Discharge Elimination System (NPDES) permit No. 2PR00240*BD. Mr. Jeff Lanum, Director of Maintenance, and Mr. John Kincaid, Operator, were present and provided information on the operation of the plant.

At the time of the inspection, the treatment facility was in operation. The contents of the aeration tanks were brown with good roll. The final discharge from the plant was visually clear. We also discussed the Operator of Record requirement to address the non-submittal of Discharge Monitoring Reports (DMRs).

Our review of your DMRs (2/1/2012 – 8/1/2013) for this facility indicated the non-submittal of DMRs in June and July of 2013. The non-submittal of DMRs is a NPDES permit violation. Please inform this office in writing within 10 days as to the reasons for this violation. Your response must include the actions that will be taken to return to compliance. Please be advised that failure to comply with your NPDES permit may result in enforcement action pursuant to Ohio Revised Code (ORC) Chapter 6111.

Our completed inspection form is enclosed for your review. Should you have any questions, please contact me at 419-373-3021.

Yours truly,



Jason Ko
Division of Surface Water

/jlm

Enclosures

pc: Marion County Health Department

ec: Tracking

OHIO ENVIRONMENTAL PROTECTION AGENCY
OPERATION AND MAINTENANCE INSPECTION

NPDES Permit No. 2PR00240

Facility Name: Morning View Pointe Expiration Date: June 30, 2017
 Facility Address: 677 Marion-Cardington Road Date: 8/21/2013 Time: 11:30 am
 City: Marion County: Marion Township: Pleasant
 Name and Address of Owner: Morning View Pointe, 677 Marion-Cardington Road, Marion, Ohio
 Person Contacted: Jeff Lanum - Maintenance & John Kincaid - Operator Owner Phone: (740) 262-2135
 Flow Design: 7,000 GPD Present 4,000 GPD (estimated)
 Trib. Pop. 30 beds (estimated) Weather at time of inspection: Temp 80°F - sunny
 OEPA Personnel: Jason Ko District: NWDO

1. Plant Effluent - Mark Severity No.

No.	Severity Description	No.	Turbidity	No.	Odor	No.	Color
0	None	X	Clear	X	None	X	Colorless
1	Mild						
2	Moderate		Light Solids		Musty		Grey
3	Serious						
4	Extreme		Heavy Solids		Septic		Black

Effect of effluent on Receiving Stream Name: Not Observed

No.	Severity Description	No.	Turbidity	No.	Odor	No.	Color
0	None		Clear		None		Colorless
1	Mild						
2	Moderate		Light Solids		Musty		Grey
3	Serious						
4	Extreme		Heavy Solids		Septic		Black

3. a. Plant has _____ excellent X good _____ fair _____ poor operation
 b. Plant has _____ excellent X good _____ fair _____ poor maintenance
 c. Sand filters have _____ excellent _____ good X fair _____ poor maintenance

d. Not operating at expected efficiency due to:

- (1) _____ hydraulic overload
 (2) _____ organic/ solids underload
 (3) _____ personnel inefficiency
 (4) _____ equipment failure
 (5) _____ wastes
 (6) DMR non-submittal

Disinfection: (Required May 1 thru Oct.31.)

IN OUT
X _____ Chlorination Tablets
X _____ Dechlorination Tablets
 _____ U.V

- | | | | | | |
|----------|-------|-----------------------------------|---------------------|------------------------------------|-------------|
| Yes | No | | Yes | No | Parameters: |
| <u>X</u> | _____ | Compliance with NPDES Permit | Periodic Violations | _____ | _____ |
| <u>X</u> | _____ | Adequate Plant Safety | Chronic Violation | _____ | _____ |
| <u>X</u> | _____ | Operation and Maintenance Service | Name : | <u>John Kincaid (740) 386-3768</u> | |

Frequency of Visits 2/week

Facility Name: Morning View care Center

Process	# Units	Unit	if Needed - Description and Comments
Preliminary	1	Trash Trap	Pumping Frequency: 2/year
		Grease Trap	Pumping Frequency:
		Bar Screen	
		Comminutor	
		Flow Equalization	
Aeration Equipment	2	Plant Timer <u> </u> Y <u>X</u> N Motor/ Blower Unit	Cycle Time: ON ½ hour & OFF ½ hour
Secondary Treatment	2	Aeration Tank	Color : Brown; good roll Adequate Aeration: Y <u>X</u> N <u> </u>
Final Settling	1	Clarifier	w/ 2 hoppers
	2	Sludge Return	In <u>X</u> Out <u> </u>
	1	Surface Skimmer	In <u>X</u> Out <u> </u>
		Fixed Media Clarifier	
Tertiary Treatment	2	Surface Sand Filter	
		Polishing Pond	
		Other	
Disinfection	IN	Chlorine Tube Feeder	
	IN	Dechlorination Tube Feeder	
		Ultraviolet (UV)	
Flow Metering	IN	Elapsed Pump Time	Hour meter at the dosing pumps
		Recorder (continuous total)	
Pumps		Raw Wastewater (type)	
	2	Sand Filter Effluent Dosing	
Sludge Handling	IN	Aerated Storage Tank	1 unit
		Sludge Drying Bed	
Sludge Disposal	IN	Municipal POTW	Haul to City of Marion
		Landfill	
		Land Application	
Advanced Treatment		Post Aeration	
		Spray Irrigation	
		Other	