



John R. Kasich, Governor  
Mary Taylor, Lt. Governor  
Scott J. Nally, Director

Re: Lucas County  
Envirosafe Services of Ohio, Inc  
NPDES Permit

September 12, 2013

Mr. Kristofer C. Mann  
Environmental Specialist  
Envirosafe Services of Ohio, Inc.  
876 Otter Creek Road  
Oregon, Ohio 43616

Dear Mr. Mann:

On August 22, 2013, I met with you to conduct an inspection of the facility's permitted discharge outfalls. In particular, we inspected outfalls, 001, 003, 004, and 012 because suspended solids violations from these outfalls were reported in the recent months.

You indicated that due to recent earth moving activities in the vicinity of areas contributing to these outfalls, some solids (silt) have not settled prior to discharge. You indicated that filter fabric will be installed at some of the outfall locations and end of pipe cleaning will take place to improve the quality of the discharged water.

Please update our office of the progress you make into ensuring the facility's compliance with discharge limits as soon as improvements are implemented. If you have any questions, please contact me at [naajy.abdullah@epa.ohio.gov](mailto:naajy.abdullah@epa.ohio.gov) or (419) 373-3017.

Sincerely,



Naajy Abdullah, P.E.  
Division of Surface Water

/jlm

Enclosure

ec: Tracking

## NPDES COMPLIANCE INSPECTION REPORT

### Section A: National Data System Coding

Permit #	NPDES	Yr/Mo/Day	Inspection Type	Inspector	FacType
21N00013	OH0053864	2013/08/22	C	S	2

### Section B: Facility Data

Name and Location of Facility Inspected  EnviroSAFE Services of Ohio, Inc 876 Otter Creek Road Oregon, Ohio 43616	Entry Time	Permit Effective Date
	9:30 a.m.	10/1/2012
	Exit Time	Permit Expiration Date
	10:15 a.m.	7/31/2015

Name(s) and Title(s) of On-Site Representative(s)	Phone Number(s)
Kristofer Mann, Environmental Specialist	(419) 698-3500

Name, Address and Title of Responsible Official	Phone Number
Kenneth Humphrey Environmental Affairs Director 876 Otter Creek Road Oregon, Ohio 43616	(419) 698-3500

### Section C: Areas Evaluated During Inspection (S = Satisfactory, M = Marginal, U = Unsatisfactory, N = Not Evaluated)

<input checked="" type="checkbox"/> S Permit	<input type="checkbox"/> N Flow Measurement	<input type="checkbox"/> N Pretreatment
<input type="checkbox"/> N Records/Reports	<input type="checkbox"/> N Laboratory	<input type="checkbox"/> N Compliance Schedules
<input type="checkbox"/> M Operations & Maintenance	<input checked="" type="checkbox"/> S Effluents	<input checked="" type="checkbox"/> S Self-Monitoring Program
<input checked="" type="checkbox"/> S Facility Site Review	<input type="checkbox"/> N Sludge Storage/Disposal	<input type="checkbox"/> Other

### Section D: Summary of Findings/Comments (Attach additional sheets if necessary)

Outfalls 001, 003, 004, and 012 were inspected and were not discharging at time of inspection.

 Naajiv Abdulhadi, P.E. Name(s) and Signature(s) of Inspector(s)	9/9/2013 Date	Ohio EPA, Northwest District Office
 Tom Poffenbarger, P.E. Name and Signature of Reviewer	9/9/2013 Date	Ohio EPA, Northwest District Office