



John T. Kasich, Governor
Frank Taylor, Lt. Governor
Scott L. Walz, Director

September 18, 2013

Rich Conie
Maronda Homes, Inc.
3811 Twin Creeks Drive
Columbus, OH 43204

**Re: Bixby Grove, Sec. 3 / Franklin County
Construction Storm Water Permit 4GC00517**

Dear Mr. Conie:

This letter is written in follow-up to a construction storm water inspection that I conducted on September 6, 2013, at Bixby Grove, Section 3, located along Groveport Road, in Franklin County. The purpose of the inspection was to evaluate compliance with the General Storm Water Permit Associated with Construction Activities. During the inspection, I noted the following:

Sediment Controls and Maintenance:

There was no active construction during my inspection at the Bixby Grove Subdivision. The entire site was stabilized with vegetation.

If you have any questions regarding this letter or the inspection, please do not hesitate to contact me at our Central District Office at (614) 728-3851.

Sincerely,

Gregory L. Sanders
Environmental Specialist
Division of Surface Water
Central District Office

GS/slw Bixby Grove, Sec. 3, September 6, 2013