



100 years and moving forward

John E. Kasich, Governor  
Mary Taylor, Lt. Governor  
Robert J. Kelly, Director

September 23, 2013

Jeff Acuff  
Mountain Agency LLC  
401 Milford Parkway, Suite A  
Milford, Ohio 45150

**RE: Construction Storm Water Inspection at Jeff Wyler Chevrolet / Franklin County  
Permit Number: 4GC04115 \*AG**

Dear Mr. Acuff:

This letter is written regarding a storm water inspection conducted by Jerome Hoke and Elizabeth Pleta of the Ohio EPA at Jeff Wyler Chevrolet located at 5885 Gender Road on September 11, 2013. The purpose of the inspection was to evaluate compliance with the General Storm Water Permit associated with Construction Activities. During the inspection, our staff noted the following issues associated with construction activities at this site:

**Sediment and Erosion Control:**

- The centralized sediment basin is currently modified for Post Construction (See Figure 1). A temporary riser and/or skimmer is required within ten (10) days from receipt of this letter to properly modify the basin for sediment control and ensure compliance with the General Permit.
- The concrete washout containment area appears to be close to overflowing. Maintenance is expected within three (3) days from receipt of this letter.

If you have any questions regarding this letter or the inspection, please do not hesitate to contact me at our Central District Office at 614-728-3844 or email at [harry.kallipolitis@epa.state.oh.us](mailto:harry.kallipolitis@epa.state.oh.us).

Sincerely

Harry Kallipolitis  
Storm Water Coordinator  
Ohio EPA  
Division of Surface Water

c: Jeff Bohne, Water Quality Supervisor, DSW / CDO

HK0slw Jeff Wyler Chevrolet 9-11-13

City of...  
Water Department  
Photo By: Jerome Hoke  
2008



Figure 1: Sediment basin requires temporary riser and/or skimmer.

City of...  
Water Department  
Photo By: Jerome Hoke  
2008



Figure 2: Concrete wa...hout requires maintenance