



City of Cleveland
Frank G. Jackson, Mayor

Department of Public Health
Division of Air Quality
75 Erieview Plaza, Second Floor
Cleveland, Ohio 44114-1839
216/664-2297 • Fax: 216/420-8047
www.clevelandhealth.org

**SERVING OHIO EPA AS AGENCY 13
FOR CUYAHOGA COUNTY**

**CERTIFIED MAIL 7012 2210 0000 5209 0885
RETURN RECEIPT REQUESTED**

May 20, 2013

Tony Gorczyca
Owner
Baltic Clifton Shell
17777 Bagley Road
Middleburg Heights, Ohio 44130

FACILITY ID: 13-18-00-6000

**RESOLUTION OF VIOLATIONS
NOTICE OF VIOLATION FOLLOW-UP LETTER**

Dear Mr. Gorczyca:

On March 15, 2013, the Cleveland Division of Air Quality (CDAQ) inspected Baltic Clifton Shell located at 9510 Baltic Road in Cleveland.

On March 19, 2013, CDAQ issued a Notice of Violation requiring Baltic Clifton Shell to perform an Air-to-Liquid (A/L) Ratio and Static Leak test for Emission Unit (EU) G001: Stage I and Stage II Gasoline Dispensing Facility: Gilbarco, and submit the test results within thirty (30) days of the test. CDAQ also requested that Baltic Clifton Shell obtain a 2012 City of Cleveland permit to operate by submitting city air contaminant source fees.

On April 11, 2013, Baltic Clifton Shell performed and passed the required A/L Ratio and Static Leak tests.

On April 29, 2013, Baltic Clifton Shell submitted 2012 City of Cleveland air contaminant source fees.

On May 20, 2013, CDAQ received a copy of the passing test results.

The appropriate steps were taken to bring the source into compliance. CDAQ has determined that no further enforcement action is warranted at this time, but reserves its right to take such action in the future if necessary.

CDAQ issues this letter with Ohio EPA's concurrence and does not excuse any violations of local, state and federal laws or regulations regarding air pollution control. Violations of air pollution control laws may be pursued in local court or referred to Ohio EPA or U.S. EPA for further enforcement action.



Should you have any questions, please call Bryan Sokolowski at (216) 420-7663. All correspondence with CDAQ must include the Ohio EPA facility identification number for Baltic Clifton Shell: 13-18-00-6000.

Sincerely,

A handwritten signature in cursive script that reads "Valencia White".

Valencia White
Chief of Enforcement, CDAQ

VW/BS Handwritten initials "BS" inside a circle.

cc: John Paulian, Ohio EPA Central Office
Brian Dickens, U.S. EPA Region V
L:\Data\Facilities\1318006000\2013-3-15 ROV+NEAR.docx