

**SENDER: COMPLETE THIS SECTION**

- Complete items 1, 2, and 3. Also complete item 4 if Restricted Delivery is desired.
- Print your name and address on the reverse so that we can return the card to you.
- Attach this card to the back of the mailpiece, or on the front if space permits.

1. Article Addressed to:  
Christina Hardwick  
Pearl / Bagley Shell  
7250 Pearl Rd.  
Middleburg Hts., OH 44130

**COMPLETE THIS SECTION ON DELIVERY**

A. Signature  Agent  
**X**  Addressee

B. Received by (Printed Name) C. Date of Delivery

D. Is delivery address different from item 1?  Yes  
If YES, enter delivery address below:  No



3. Service Type  
 Certified Mail  Express Mail  
 Registered  Return Receipt for Merchandise  
 Insured Mail  C.O.D.

4. Restricted Delivery? (Extra Fee)  Yes

2. Article Number (Transfer from service label) 7009 3410 0002 1934 0915



City of Cleveland  
Frank G. Jackson, Mayor

Department of Public Health  
Division of Air Quality  
75 Erieview Plaza, Suite 200  
Cleveland, Ohio 44114-1839  
216/664-2297 • Fax: 216/420 8047  
www.clevelandhealth.org

**SERVING OHIO EPA AS AGENCY 13  
FOR CUYAHOGA COUNTY**

**CERTIFIED MAIL 7009 3410 0002 1934 0915  
RETURN RECEIPT REQUESTED**

September 10, 2010

Christina Hardwick  
Pearl/Bagley Shell  
7250 Pearl Road  
Middleburg Heights, OH 44130

**FACILITY ID: 13-18-34-6810  
NOTICE OF VIOLATION FOLLOW-UP LETTER**

Dear Mrs. Hardwick:

On July 30, 2010, the Cleveland Division of Air Quality (CDAQ) issued a Notice of Violation requiring Pearl/Bagley Shell to complete the necessary repairs, conduct a re-test of the blockage, conduct the Air-to-Liquid Ratio test and submit the test results within thirty (30) days of receipt of the letter. CDAQ is in receipt of a corrective action plan dated September 9, 2010 at which time CDAQ witnessed a retest of the blockage. The blockage test passed at this time. The Static Leak and Air-to-Liquid Ratio tests also passed at this time.

The corrective action plan was received in a timely manner and appropriate steps were taken to bring the source into compliance. CDAQ has determined that no further enforcement action is warranted at this time, but reserves its right to take such action in the future if necessary.

CDAQ issues this letter with Ohio EPA's concurrence and does not excuse any violations of local, state and federal laws or regulations regarding air pollution control. Violations of air pollution control laws may be pursued in local court or referred to Ohio EPA or U.S. EPA for further enforcement action. Should you have any questions, please call Megan Murphy at 216-664-4258. All correspondence with CDAQ must include the Ohio EPA facility identification number for Pearl/Bagley Shell: 13-18-34-6810.

Sincerely,

*Grinda Kimmy for G.B.*  
George Baker  
Chief of Enforcement, CDAQ

GB/mm

cc: John Paulian, Ohio EPA Central Office  
Lisa Holscher, U.S. EPA Region V  
Facility File and L:\Data\Facilities\1318346810\2010-7-29 NEAR.doc



**CLEVELAND DIVISION OF AIR QUALITY**  
**GDF INSPECTION REPORT**

REVISED: 05/16/2007



DAPC - APPENDIX N (GDF)

**STATIC LEAK TEST RESULTS**

True North  
 Pearl / Bagley Shell  
 13 18 34 68 10

Stage II System: Vapor Balance  Vacuum Assist

Stage I System: Two point  Coaxial  Manifold? Aboveground  Underground

Tank #	1	2	3	
Product Grade	Reg Unl	Mid Unl	Pre Unl	
Actual Tank Capacity, gallons	9438	9438	9438	
Gasoline Volume	5474	2430	2587	
Ullage, gallons (#2-#3)	3964	7008	6851	17823
Initial Pressure, inches H <sub>2</sub> O				+0.25
Number of Nozzles Served by Tank				18
Test Location: Stage I VC or Stage II Riser				Stage I VC
Pressure After 1 Minute, inches H <sub>2</sub> O				2.00
Pressure After 2 Minutes, inches H <sub>2</sub> O				2.00
Pressure After 3 Minutes, inches H <sub>2</sub> O				2.00
Pressure After 4 Minutes, inches H <sub>2</sub> O				2.00
Final Pressure After 5 Minutes, inches H <sub>2</sub> O				2.00
Allowable Final Pressure				1.93

Static Leak Test Results: Pass  Fail  which tanks failed? \_\_\_\_\_

Notes: \_\_\_\_\_

**DYNAMIC PRESSURE TEST RESULTS**

Quantity of gasoline introduced into Stage II, (gallons): 2 Riser  Bellows

Nozzle #	40 CFH 0.16" Max	60 CFH 0.35" Max	80 CFH 0.62" Max	Pass / Fail
1+2	.10/10	.18/10	.29/23	Pass
3+4	.10	.19	.27	Pass
5+6	.09	.17	.25	Pass

Nozzle #	40 CFH 0.16" Max	60 CFH 0.35" Max	80 CFH 0.62" Max	Pass / Fail

Did the gauge needle pulsate or peg at any flow rate during the test? Yes  No

Dynamic Pressure Results: Pass  Fail

Notes: one dropout tank found, two siphon lines need to be

05/16/07 opened for blockage -> bad check valve Page 2 of 3



**SENDER: COMPLETE THIS SECTION**

- Complete items 2 and 3. Also complete item 4 if Restricted Delivery is desired.
- Print your name and address on the reverse so that we can return the card to you.
- Attach this card to the back of the mailpiece, or on the front if space permits.

1. Article Addressed to:  
Christina Hardwick  
Pearl / Bagley Shell  
7250 Pearl Rd.  
Middleburg Hts. OH 44130

2. Article Number  
(Transfer from service label)

**COMPLETE THIS SECTION ON DELIVERY**

A. Signature  
*XKCC*  Agent  
 Addressee

B. Received by (Printed Name) C. Date of Delivery

D. Is delivery address different from item 1?  Yes  
If YES, enter delivery address below:  No

3. Service Type  
 Certified Mail  Express Mail  
 Registered  Return Receipt for Merchandise  
 Insured Mail  C.O.D.

4. Restricted Delivery? (Extra Fee)  Yes

7009 3410 0002 1934 0588