



City of Cleveland

Frank G. Jackson, Mayor

Department of Public Health
Division of Air Quality
1925 St. Clair Avenue
Cleveland, Ohio 44114-2080
216/664-2297 • Fax: 216/420-8047
www.clevelandhealth.org

**SERVING OHIO EPA AS AGENCY 13
FOR CUYAHOGA COUNTY**

**CERTIFIED MAIL 7002 2030 0001 1808 4055
RETURN RECEIPT REQUESTED**

09/14/2007

Tim Thomas
Southland Automotive
7026 W. 130th Street
Middleburg Heights, Ohio 44130

**FACILITY ID: 1318346812
NOTICE OF VIOLATION FOLLOW-UP LETTER**

Dear Mr. Thomas:

On 07/31/2007, the Cleveland Division of Air Quality (CDAQ) issued a Notice of Violation to Southland Automotive for failure to conduct an Air-to-Liquid Ratio test and a Static Leak test. CDAQ is in receipt of passing Stage II test results dated 08/28/2007.

The corrective action plan was received and appropriate steps were taken to bring the source into compliance. CDAQ has determined that no further enforcement action is warranted at this time, but reserves its right to take such action in the future if necessary.


CDAQ issues this letter with Ohio EPA's concurrence and does not excuse any violations of local, state and federal laws or regulations regarding air pollution control. Violations of air pollution control laws may be pursued in local court or referred to Ohio EPA or U.S. EPA for further enforcement action. Should you have any questions, please call Mike Samec at 216-420-7682. All correspondence with CDAQ must include the Ohio EPA facility identification number for Southland Automotive: 1318346812.

Sincerely,

George Baker
Chief of Enforcement, CDAQ

GB/ms

cc: Richard Nemeth and Michael J. Krzywicki, CDAQ
John Paulian, Ohio EPA Central Office
Facility File and L:\Data\Facilities\1318346812\2007-09-14 NEAR.doc



TANK INTEGRITY SERVICES

Compliance Testing of:

- Storage Tanks & Product Lines
- Stage II Vapor Recovery Systems
- Corrosion Protection Testing & Design

DATE: September 18, 2007

ATTN: Mike Samec / Cleveland Air Quality

FAX: 216-441-7406

FROM: Deb Hamer

RE: 2007 SOUTHLAND AUTOMOTIVE STAGE II TEST RESULTS

Total # of Pages = 3. (including cover)



TANK INTEGRITY SERVICES, INC.

North Royalton, Ohio 44133

Phone: (440)237-9200

Fax: (440)582-5119

LOCATION DATA: STAGE II VAPOR RECOVERY SYSTEM TEST DATA FORM

Location Name: <u>SOUTHLAND AUTOMOTIVE</u>	Location #: <u>N/A</u>	Job #: <u>9477</u>	Date: <u>8/28/2007</u>
Address: <u>7026 W 130TH ST</u>		Tester: <u>KARL MOSKAL</u>	
City/State: <u>MIDDLEBURG HTS OH 44130</u>	Inspector: _____		

Stage I Type:	Two Point: <input checked="" type="checkbox"/>	Coaxial: <input type="checkbox"/>	Poppeted? <input type="checkbox"/>	Manifolded: UG <input checked="" type="checkbox"/> AG <input type="checkbox"/>	<u>0</u> Feet AG
Stage II Type:	Vapor Balance: <input type="checkbox"/>	Vacuum Assist: <input checked="" type="checkbox"/>	Type: <u>GV</u>		
	Drop Out: <input checked="" type="checkbox"/>	Sealed: <input checked="" type="checkbox"/>	Syphon: <input checked="" type="checkbox"/>		

STATIC LEAK TEST RESULTS:

Product Type:	<u>RULE</u>	<u>RULE</u>	<u>RULE</u>	<u>RULE</u>	TOTALS
Actual Tank Capacity (Gallons):	<u>9,520</u>	<u>7,734</u>	<u>0</u>	<u>0</u>	<u>17,254</u>
Gasoline Volume (Gallons):	<u>3,929</u>	<u>1,409</u>	<u>0</u>	<u>0</u>	<u>5,338</u>
Ullage (Gallons):	<u>5,591</u>	<u>6,325</u>	<u>0</u>	<u>0</u>	<u>11,916</u>
Initial Pressure of UST:	Inches Water				<u>0.00</u>
Nozzle Served by Tank (s):	Quantity				<u>6</u>
(A) Stage I Coupler / (B) Stage II Riser:	Test Location				<u>A</u>
Initial Pressure:	Inches Water				<u>2.00</u>
Pressure After 1 Minute:	Inches Water				<u>2.00</u>
Pressure After 2 Minutes:	Inches Water				<u>2.00</u>
Pressure After 3 Minutes:	Inches Water				<u>2.00</u>
Pressure After 4 Minutes:	Inches Water				<u>2.00</u>
Pressure After 5 Minutes:	Inches Water				<u>2.00</u>
Allowable Final Pressure:	Table IA or IB				<u>1.92</u>
Test Status:	Pass or Fail				<u>PASS</u>

DYNAMIC PRESSURE TEST RESULTS:

Riser / Nozzle #	40 CFH .16 Max	60 CFH .35 Max	80 CFH .62 Max	Pass / Fail	Riser / Nozzle #	40 CFH .16 Max	60 CFH .35 Max	80 CFH .62 Max	Pass / Fail

Gallons of gasoline introduced into Stage II riser: _____ Did gauge pulsate or peg at any flow rate during test? _____

COMMENTS: _____



TANK INTEGRITY SERVICES, INC.

North Royalton, Ohio 44133

Phone: (440)237-9200

Fax: (440)582-5119

AIR TO LIQUID RATIO (A/L) TEST DATA FORM

LOCATION DATA:

Location Name: <u>SOUTHLAND AUTOMOTIVE</u>	Location #: <u>N/A</u>	Job #: <u>9477</u>	Date: <u>8/28/2007</u>
Address: <u>7026 W 130TH ST</u>		Tester: <u>KARL MOSKAL</u>	
City/State: <u>MIDDLEBURG HTS OH 44130</u>	Inspector: _____		

Stage II System Type: Vacuum Assist:

Manufacturer: GV

Hasstech: _____

RESULTS:

Disp#	Nozzle Model#	Gas Grade	Gas		A/L Ratio	Pass / Fail	Disp#	Nozzle Model#	Gas Grade	Gas		A/L Ratio	Pass / Fail
			Loaded Gal	Dispensing Rate-GPM						Loaded Gal	Dispensing Rate-GPM		
1	ICVN	RUL	2.657	6.44	.99	PASS	6	ICVN	RUL	2.539	6.15	.94	PASS
1	ICVN	MUL	2.553	7.44	1.00	PASS	6	ICVN	MUL	2.566	7.32	.99	PASS
1	ICVN	PUL	2.568	7.74	1.01	PASS	6	ICVN	PUL	2.543	7.11	.97	PASS
2	Richards	RUL	2.549	6.23	1.05	PASS							
2	Richards	MUL	2.550	7.16	1.03	PASS							
2	Richards	PUL	2.558	7.16	1.01	PASS							
3	ICVN	RUL	2.577	6.86	1.04	PASS							
3	ICVN	MUL	2.589	7.50	1.06	PASS							
3	ICVN	PUL	2.580	7.38	1.06	PASS							
4	12VW	RUL	2.539	6.19	1.10	PASS							
4	12VW	MUL	2.556	6.85	1.10	PASS							
4	12VW	PUL	2.575	6.31	1.07	PASS							
5	ICVN	RUL	2.548	6.35	.92	PASS							
5	ICVN	MUL	2.531	7.68	.97	PASS							
5	ICVN	PUL	2.557	7.61	.95	PASS							

COMMENT:

S/N: VS-0554

Calibration Date: 08/30/06

Southland Automotive
7026 W130th Street
Middleburg Hts., Ohio 44130
Facility ID 1318346812

September 6, 2007

Mike Samec
Cleveland Division of Air Quality
1925 St. Clair Avenue NE
Cleveland, Ohio 44114-2080

Mr. Samec,

Regarding your inspection of this facility on July 31, 2007, testing was completed and passed on August 28, 2007. We are awaiting written copies of the test and will forward them when received. The Permit By Rule is being applied for.

Thank You.

Tim Thomas

A handwritten signature in cursive script, appearing to read "Tim Thomas", written in black ink.

RECEIVED
SEP 13 2007
CIVIL ENGINEERING
DIVISION



City of Cleveland
Frank G. Jackson, Mayor

Department of Public Health
Division of Air Quality
1925 St. Clair Avenue
Cleveland, Ohio 44114-2080
216/664-2297 • Fax: 216/420-8047
www.clevelandhealth.org

**SERVING OHIO EPA AS AGENCY 13
FOR CUYAHOGA COUNTY**

VIA HAND DELIVERY
 VIA CERTIFIED MAIL: _____

Date: 7/30/07

Owner: Tim Thomas

Facility Name: Southland Automotive

Address: 7026 W130th Middleburg Hts Oh 44130

Inspector: Mike Samec

FACILITY ID: ~~1318346812~~ 1318346812
NOTICE OF VIOLATION: STAGE II REQUIREMENTS

The Cleveland Division of Air Quality (CDAQ) inspected the above reference facility. This letter serves as notification that you are operating sources in violation of the following applicable air statutes, air regulations, or air permit conditions. Violations are noted by checkboxes before the paragraph; each checked item is a violation of the Ohio Administrative Code (OAC) noted in that paragraph, and a separate violation of Ohio Revised Code (ORC) Section 3704.05(G).

- Failure to provide a copy of the most recent permit-to-operate (PTO) issued to your facility. *Violation of OAC 3745-21-09(DDD)(3)(a)(v)*
- Failure to provide a copy of the most recent PTO application and emissions activity category form for your facility. *Violation of OAC 3745-21-09(DDD)(3)(a)(iv)*
- Failure to submit a PTO application and emissions activity category form for your facility. *Violation of OAC 3745-35-02(A)*
- Failure to submit a permit-to-install (PTI) application and emissions activity category form for your facility. *Violation of OAC 3745-31-02(A)(1)*
- Failure to conduct an Air-to-Liquid Ratio test within 12 months on your gasoline dispensing facility. *Violation of OAC 3745-21-09(DDD)(2)(f)*
- Failure to conduct a Static Leak test within 12 months on your gasoline dispensing facility. *Violation of OAC 3745-21-09(DDD)(2)(f)*
- Failure to conduct a Dynamic Pressure test within 5 years on your gasoline dispensing facility. *Violation of OAC 3745-21-09(DDD)(2)(d)*
- Failure to provide a copy of the most recent Stage II test results for your gasoline dispensing facility. *Violation of OAC 3745-21-09(DDD)(3)(a)(ii)*
- Failure to provide a copy of the certificate issued to the Stage II Compliance Specialist for your gasoline dispensing facility. *Violation of OAC 3745-21-09(DDD)(3)(a)(vi)*
- Failure to submit Stage II test results to CDAQ within 30 days of completing the test. *Violation of OAC 3745-21-09(DDD)(2)(c)*
- Your gasoline dispensing facility has been issued PTI _____. The violations listed above are also violations of this PTI and ORC Section 3704.05(C).
- Your gasoline dispensing facility has been issued a PTO on _____. The violations listed above are also violations of this PTO and ORC Section 3704.05(C).



Unless you undertake some type of corrective action with respect to the above noted violations, you will remain in non-compliance. Your written response to this letter must be received by CDAQ within fourteen (14) days of your receipt of this letter. If there is insufficient time to correct the alleged violations within this timeframe, your response must include a timeline for correcting the alleged violations. Your written response should be addressed to the inspector listed on the first page of this letter and mailed to:

Cleveland Division of Air Quality
1925 St. Clair Avenue NE
Cleveland, Ohio 44114-2080

Violations of Ohio air pollution laws and /or permit terms and conditions are subject to the penalties stipulated in Ohio Revised Code Section 3704.99(A), which allows fines of not more than twenty-five thousand dollars or imprisonment for not more than one year, or both, for each violation.

Free assistance with state and/or federal regulations, rules, laws or permit conditions can be provided at no charge through Ohio EPA Office of Compliance Assistance and Pollution Prevention (OCAPP). OCAPP can be contacted at <http://www.epa.state.oh.us/ocapp> or (614) 644-3469 or (800) 329-7518. CDAQ makes no guarantee that the facility will meet the qualifying guidelines established by the OCAPP.

Facilities that want to investigate methods of pollution prevention to reduce raw material usage and waste production can contact the Ohio EPA Office of Compliance Assistance and Pollution Prevention (OCAPP). OCAPP can be contacted at <http://www.epa.state.oh.us/ocapp> or (614) 644-3469 or (800) 329-7518 and there is no charge for their services.

CDAQ issues this letter with Ohio EPA's concurrence. The failure to mention any specific violation does not excuse any violations of local, state and federal laws or regulations regarding air pollution control. Violations of air pollution control laws may be pursued in local court or referred to Ohio EPA or U.S. EPA for further enforcement action. Should you have any questions, please call CDAQ at 216-664-2297 and ask for the inspector on the first page of this letter. All correspondence with CDAQ must include the Ohio EPA facility identification number listed on the first page of this letter.

Sincerely,

George Baker
Chief of Enforcement, CDAQ

cc: Richard Nemeth and Michael J. Krzywicki, CDAQ
John Paulian, Ohio EPA Central Office
Lisa Holscher, U.S. EPA Region V
Facility File