

1652 100064



**AKRON REGIONAL  
AIR QUALITY MANAGEMENT DISTRICT**

*Agent of the Ohio Environmental Protection Agency • Division of the Akron Health Department  
Serving Medina, Portage and Summit Counties*

TELEPHONE: (330) 375-2480  
FAX: (330) 375-2482

**L. M. Malcolm, P.E.**  
Administrator

February 11, 2009

Mr. Jeff Wolf  
North High Auto Service  
710 N. High Street  
Wadsworth, OH 44281

Dear Mr. Wolf:

On February 9, 2009, a representative of the Akron Regional Air Quality Management District (ARAQMD) inspected the North High Auto Service gasoline dispensing facility located at 710 High Street in Wadsworth to determine compliance with OAC 3745-21-09 (DDD) regarding Stage II vapor recovery.

**Inspection results/Deficiencies:**

Equipment: This facility failed Stage II testing on 2/9/08. **Repair and retesting are required within 30 days.**

ARAQMD file: A review of our records found that this facility is in **violation of OAC rule 3745-21-09 (DDD) (2)**, as you failed to successfully complete Stage II testing in 2008. This facility failed testing on 12/4/08.

Please correct any deficiencies noted. This facility will be inspected on an annual basis for compliance with the Stage II vapor recovery rule. It is required that you keep record keeping information at a readily available location for inspection. For this Agency, it is requested that you keep copies of the required information at each individual location where all employees can access them.

Thank you for your cooperation and assistance in this matter. If you have any questions, please contact me at 330/375-2480 x6053.

Sincerely,

Susan Anderson  
Sanitarian II

SA  
Certified Mail

CITICENTER - SUITE 904  
146 SOUTH HIGH STREET • AKRON, OHIO 44308  
*An equal opportunity employer and provider of services - CRA 1964*