

AKRON REGIONAL  
AIR QUALITY MANAGEMENT DISTRICT

Agent of the Ohio Environmental Protection Agency • Division of the Akron Health Department  
Serving Medina, Portage and Summit Counties

TELEPHONE: (330) 375-2480  
FAX: (330) 375-2402

L. M. Malcolm, P.E.  
Administrator

January 30, 2008

Mr. Basem I. Ali  
Giant Ohio LLC  
3904 Corporex Park Drive #150  
Tampa, FL 33619

Dear Mr. Ali:

A representative of the Akron Regional Air Quality Management District (ARAQMD) inspected the following BP Oil Company gasoline dispensing facilities to determine compliance with OAC 3745-21-09 (DDD) regarding Stage II vapor recovery:

<u>Date</u>	<u>Site</u>	<u>Address</u>	<u>City</u>
1/14/08	436	571 W. Waterloo Road	Akron 1677 010857
1/18/08	443	4415 State Route 43	Kent 1667 040107
1/23/08	430	820 High Street	Wadsworth 1652 100058
1/24/08	432	3705 Cleveland-Massillon Road	Norton 1677 020111
1/25/08	438	3171 S. Arlington Road	Akron 1677 000531

**Inspection results/Deficiencies:**

<u>Site</u>	<u>Deficiency</u>
436	Record keeping: No record keeping was available for review. <b>Giant Ohio BP #436 is in violation of OAC rule 3745-21-09 (DDD)(3) which specifies what records are to be kept.</b> A certificate of Stage II vapor recovery training must be obtained and a copy kept in the Station file.
	Equipment: This facility failed Stage II testing on 1/14/08. Timely repair and retesting are required.

CITICENTER - SUITE 904  
146 SOUTH HIGH STREET • AKRON, OHIO 44308  
An equal opportunity employer and provider of services - CRA 1964



Printed on Recycled Paper

Mr. Basem I. Ali  
Page 2  
January 30, 2008

<u>Site</u>	<u>Deficiency</u>
443	Record keeping: No record keeping was available for review. <b>Giant Ohio BP #443 is in violation of OAC rule 3745-21-09 (DDD)(3) which specifies what records are to be kept.</b> A certificate of Stage II vapor recovery training must be obtained and a copy kept in the Station file.  Equipment: This facility failed Stage II testing on 1/18/08. Timely repair and retesting are required.
430	Record keeping: A certificate of Stage II training must be obtained and a copy of it kept in the Station file.  Equipment: This facility failed Stage II testing on 1/23/08. Timely repair and retesting are required.
432	Record keeping: No record keeping was available for review. <b>Giant Ohio BP #432 is in violation of OAC rule 3745-21-09 (DDD)(3) which specifies what records are to be kept.</b> A certificate of Stage II vapor recovery training must be obtained and a copy kept in the Station file.  Equipment: This facility failed Stage II testing on 1/24/08. Timely repair and retesting are required.
438	Record keeping: A certificate of Stage II training must be obtained and a copy of it kept in the Station file.

Please correct the deficiencies noted. These facilities will be inspected on an annual basis for compliance with the Stage II vapor recovery rule. It is required that you keep record keeping information at a readily available location for inspection. For this Agency, it is requested that you keep copies of the required information at each individual location where all employees can access them.

Thank you for your cooperation and assistance in this matter. If you have any questions, please contact me at 330/375-2480 x6053.

Sincerely,



Susan Anderson  
Sanitarian II

SA