



AKRON REGIONAL  
AIR QUALITY MANAGEMENT DISTRICT

Agent of the Ohio Environmental Protection Agency • Division of the Akron Health Department  
Serving Medina, Portage and Summit Counties

TELEPHONE: (330) 375-2480  
FAX: (330) 375-2402

L. M. Malcolm, P.E.  
Administrator

July 25, 2011

Mr. Aymen Salti  
Archwood Sunoco  
745 E. Archwood Avenue  
Akron, Ohio 44306

Dear Mr. Salti:

**Subject: NOTICE OF VIOLATION –FAILURE TO COMPLETE THE STAGE II VAPOR RECOVERY SYSTEM TESTING INSTALLED AT THE ARCHWOOD SUNOCO GASOLINE DISPENSING FACILITY LOCATED AT 745 E. ARCHWOOD AVE. IN AKRON**

On June 13<sup>th</sup>, 2011 a representative of the Akron Regional Air Quality Management District inspected the Archwood Sunoco gasoline dispensing facility to determine compliance with OAC 3745-21-09 (DDD) regarding Stage II vapor recovery. At that time this facility failed Stage II testing. Repair and retesting were to be completed within 30 days. **This facility is in violation of OAC rule 3745-21-09 (DDD)(2) which specifies the testing required and its frequency.**

Stage II testing needs to be scheduled within 7 days of receipt of this letter. Archwood Sunoco is in violation of the Stage II rule for each day of operation without the completion of testing and can be fined accordingly.

Acceptance of the Stage II testing requested by this Agency does not constitute a waiver of this Agency's or the Ohio EPA's authority to seek civil penalties as provided in Section 3704.06 of the Ohio Revised Code. The determination to pursue or to decline such penalties will be made at a later date.

Thank you for your cooperation and assistance in this matter. If you have any questions, please contact me at 330/375-2480 x3950.

Sincerely,

*Nicole Bradley*  
Nicole Bradley  
Environmental Specialist

Certified

CITICENTER - SUITE 904  
146 SOUTH HIGH STREET • AKRON, OHIO 44308  
*An equal opportunity employer and provider of services - CRA 1964*

1677 011130